

0081

*Incoming
4/15/0015*

From: "Hardy, Russell" <RussellHardy@consolenergy.com>
To: "Hardy, Russell" <RussellHardy@consolenergy.com>, <pamgrubaughlittig@uta...
Date: 10/22/2007 2:50 PM
Subject: Emery Subsidence Report
Attachments: Emery Subsidence 10-19-07.pdf

CC: <karlhouskeeper@utah.gov>, <waynewestern@utah.gov>, <SteveChristensen@ut...
Please find attached the subsidence report for September .

Russell Hardy
CONSOL ENERGY
Phone: (435) 286-3513
Fax: (435) 286-3516
email: russellhardy@consolenergy.com

----- "This communication,
including any attachments, may contain confidential and privileged
information that is subject to the CONSOL Energy Inc.'s Business
Information Protection Policy. The information is intended solely
for the use of the intended recipient(s). If you are not an
intended recipient, you are prohibited from any use, distribution,
or copying of this communication. If you have received this
communication in error, please immediately notify the sender and
then delete this communication in its entirety from your system."

Consolidation Coal Emery Mine Subsidence Report for September 2007

- 9-21-07 New cracks are still forming where we are mining. PB
- 10-3-07 Panel 14 West – No new cracks have formed. BH
- 10-11-07 Panel 14 West – No new cracks have formed. BH
- 10-18-07 Panel 14 West – Some cracks are still filling in and new cracks are forming over the active mining area. The new cracks are approximately 1 inch wide. Some cracks were noticed on and near the county road and pictures were taken, see below. PB





Below is a summary of the flow data from SP-10 collected by Karla Knoop, from JBR Environmental.

Consol Emery Mine
Panel 14th West
Bryant No. 1
Flow Measurements made at dam
breach
Measurements taken by Karla Knoop

Date	Flow (gpm)
6/13/2007	77
7/24/2007	52
8/28/2007	75
9/20/2007	69